



Carbon monoxide symptoms

Symptoms of carbon monoxide poisoning are similar to those of flu: headaches, fatigue, nausea, dizzy spells, confusion and irritability.

Carbon monoxide detector locations

At least two are recommended – one in the furnace room, and one near sleeping areas.

Carbon monoxide comes from any fuel-burning appliance that is malfunctioning or improperly installed.

Potential carbon monoxide sources in the home

- 1 Blocked chimney
- 2 Portable heater
- 3 Fireplace
- 4 Gas refrigerator
- 5 Kitchen range or cooktop vent
- 6 Grill used indoors
- 7 Cracked heat exchanger in furnace
- 8 Disconnected water heater vent
- 9 Gas clothes dryer
- 10 Automobile exhaust

SOURCE: The Associated Press

DAVE CROY/THE WORLD-HERALD